

**OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla DATE: 04/13/06

CORNER DESIGNATION: 3N31, X-17, The East One-Quarter Corner of Section 34.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by D.S. Payne, under Contract No. 100, dated August 1, 1861. Record states: Set charred stake with mound, trench and pits as per insts. for qr. sec. corner.

MONUMENT AND ACCESSORIES FOUND: None.

MONUMENT MARKING DETAIL:

T3N R31E  
1/4  
S34 | S35  
2006  
PLS 1106

MONUMENT SET:

Re-established corner by single proportionate measure between the reestablished Northeast and Southeast corners of Section 34. At reestablished corner position, set a 2 3/8" brass cap on 1 1/4" x 30" galvanized iron pipe with cap 15" below ground surface. Monument marked as shown in monument marking detail.

From which:

- A silver Deep-1 magnet buried 22" below ground level bears North 55° East, 30.8 feet.
  - A blue Deep-1 magnet buried 22" below ground level bears South 34 1/2° East, 36.2 feet.
  - A purple Deep-1 magnet buried 22" below ground level bears South 43° West, 34.8 feet.
  - An orange Deep-1 magnet buried 22" below ground level bears North 42° West, 29.0 feet.
- Buried bearing object signs with all rebar accessories. Set steel fence post with witness sign 1 foot South of monument.

LOCATION AND COMMENTS: Corner is located in a farmed field 30 feet East of a farmed field line. This field line has existed in its current location for many years—see additional comments for the Northeast corner of Section 34.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 744093.77  
E = 8607673.97

FIRM: William R. Wells, PLS  
P.O. Box 1696  
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells, LSIT

/3N31X17

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-08*