

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 03/14/06

CORNER DESIGNATION: 3N31, X-5, The West One-Quarter Corner of Section 32.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by D.S. Payne, under Contract No. 100, dated August 1, 1861. Record states: Set charred stake with mound, trench and pits as per insts. for 1/4 section corner.

MONUMENT AND ACCESSORIES FOUND: None.

MONUMENT MARKING DETAIL:

T3N R31E
1
4
S31 | S32
2006
PLS 1106

MONUMENT SET:

Re-established corner by single proportionate measure between the reestablished Northeast and Southeast corners of Section 31. At reestablished corner position, set a 2 3/8" brass cap on a 1 1/4" x 30" galvanized iron pipe with cap 2" above ground level and raised a mound of stone and earth top to of cap. Cap marked as shown in monument marking detail.

From which:

A 5/8" x 24" iron rebar with 1 1/4" yellow plastic cap marked "OR PLS 1106 WA PLS 17372" bears North 40° East, 39.4 feet.

A 5/8" x 24" iron rebar with 1 1/4" yellow plastic cap marked "OR PLS 1106 WA PLS 17372" bears South 77 1/2° East, 25.1 feet.

A 5/8" x 24" iron rebar with 1 1/4" yellow plastic cap marked "OR PLS 1106 WA PLS 17372" bears South 60° West, 24.2 feet.

A 5/8" x 24" iron rebar with 1 1/4" yellow plastic cap marked "OR PLS 1106 WA PLS 17372" bears North 39° West, 29.8 feet.

Attached bearing object signs to rebar accessories. Set steel fence post with witness sign attached 1 foot South of corner.

LOCATION AND COMMENTS: Corner is located in an unfarmed area 40+- West of a washed out ditch and in line with field lines running East-West.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 744007.83
E = 8591828.50

FIRM: William R. Wells, PLS
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells, LSIT

/3N31X5

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-09