

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 04/03/06

CORNER DESIGNATION: 3N31, Z-17, The Southwest Quarter Corner of Section 35.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner established by Josiah A. Burnett, under Contract No. 92, dated September 12, 1860. Record states: Set a post for corner to Secs. 2, 3, 34 & 35. Drove charred stake and raised mound with trench, as per instructions.

MONUMENT AND ACCESSORIES FOUND: None, falls in farmed wheat field, at a North-South field line.

MONUMENT MARKING DETAIL:

T3N
R31E
S34|S35
S3|S2
T2N
2006
PLS 1106

MONUMENT SET:

Reestablished corner position on parallel of latitude between recovered S.W. corner of Section 34 and recovered corner at the Southeast corner of Section 36, holding North-South field berm for departure at corner point. At position determined by survey, set a 2 3/8" brass cap on 1 1/4" x 30" galvanized iron pipe with cap 15" below ground level in a farmed field. Monument marked as shown in monument marking detail.

From which:

A silver Deep-1 magnet buried 24" below ground level bears North 55° East, 35.6 feet.
A blue Deep-1 magnet buried 24" below ground level bears South 35° East, 41.2 feet.
A purple Deep-1 magnet buried 24" below ground level bears South 35° West, 39.3 feet.
An orange Deep-1 magnet buried 24" below ground level bears North 44° West, 30.6 feet.
Buried bearing object signs with all magnets. Set steel fence post with witness sign 1 foot South of monument.

LOCATION AND COMMENTS: Corner is located in a North-South field berm between farmed wheat fields.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 741432.69
E = 8607712.59

FIRM: William R. Wells, PLS
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells, LSIT

/3N31Z17

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-08