

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 04/03/06

CORNER DESIGNATION: 3N31, Z-21, The Southwest One-Quarter Corner of Section 36.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner established by Josiah A. Burnett, under Contract No. 92, dated September 12, 1860. Record states: Set a post for corner to Secs. 1, 2, 35 & 36. Drove charred stake and raised mound with trench, as per instructions.

MONUMENT AND ACCESSORIES FOUND: None.

MONUMENT MARKING DETAIL:

T3N
R31E
S35|S36
S2|S1
T2N
2006
PLS 1106

MONUMENT SET:

Re-established corner by single proportionate measure, on parallel of latitude, between the reestablished Southeast corner of Section 34, and the recovered Southeast corner of Section 36. At reestablished corner position, set a 2 3/8" brass cap on 1 1/4" x 30" galvanized iron pipe with cap 15" below ground level in a farmed field. Monument marked as shown in monument marking detail.

From which:

A silver Deep-1 magnet buried 24" below ground level bears North 77° East, 31.5 feet.
A blue Deep-1 magnet buried 24" below ground level bears South 14° East, 38.3 feet.
A purple Deep-1 magnet buried 24" below ground level bears South 73 1/2° West, 36.2 feet.
A orange Deep-1 magnet buried 24" below ground level bears North 4 1/2° West, 31.4 feet.
Buried bearing object signs with all magnets.

LOCATION AND COMMENTS: Corner is located in a farmed field. There are no definite features visible in the corner area.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 741458.00
E = 8612998.15

FIRM: William R. Wells, PLS
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells, LSIT

/3N31Z21

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-08

16-11-20