




OR  N PUBLIC LAND CORNER REPORT / RESTORATION REPO.  
Umatilla County Surveyor's Office

<b>SECTION</b> 18 and 19	<b>TOWNSHIP</b> 3N	<b>RANGE</b> 36E
<b>COUNTY:</b> Umatilla		<b>DATE</b> 6/20/08
<b>CORNER DESIGNATION: N-4</b>  East 1/16 corner between sections 18 and 19		<b>(Please check one)</b>
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Renewed
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Surveyed In
		<input type="checkbox"/> Referenced Out
Previous Renewals / Surveys, etc.  Originally set by U.S. Deputy Surveyor James Currin, under his contract No. 537, Dated: March 5, 1889. The surveyors field notes state " Set Basalt Stone 12x10x7 ins, 9 ins. In the ground for 1/16 Cor., Marked 1/16 on N. Face". In 1919 U.S. Indian Services Surveyor, C.E. Redfield, re-ran the lines and did not find the Original Stone. At the surveyed location he set an Iron Post. See Redfield notes, Page 239.		
<b>Monument(s) &amp; Accessories Found: (Condition &amp; Source)</b>  Found a 2" Galvanized Iron Pipe with a 2 1/2" Brass Cap, protruding 14", at a North-South-West Fence Corner.		
<b>Monument Detail:</b>  	<b>Sketch:</b>  	
<b>Monument Set (Procedures and Description):</b>		
<b>New Accessories:</b> NONE		
<b>Location &amp; Comments:</b>		<b>Compass Declination:</b>
<b>Firm / Agency</b> USKH Address: 5 N. Colville St., Walla Walla, Wa 99632		<b>SURVEYOR'S SEAL</b>
<b>Party Chief</b> Greg E. Flowers		
<b>Notes</b>		RENEWS 12/31/09 6/30/08
<b>Witness</b> Damon Locke		

08-112-c