




OR. ON PUBLIC LAND CORNER REPORT / RESTORATION REPC...
Umatilla County Surveyor's Office

SECTION 17 and 20	TOWNSHIP 3N	RANGE 36E
COUNTY: Umatilla		DATE 6/20/08
CORNER DESIGNATION: N-8 East 1/16 corner common to Sections 17 and 20.		(Please check one) <input type="checkbox"/> Condition Report Only <input type="checkbox"/> Not Found <input type="checkbox"/> Renewed <input type="checkbox"/> Unrecorded <input checked="" type="checkbox"/> Surveyed In <input type="checkbox"/> Referenced Out
Previous Renewals / Surveys, etc. This corner was originally set by U.S. Indian Services Surveyor C.E. Redfield in 1919		
Monument(s) & Accessories Found: (Condition & Source) No monuments were found		
Monument Detail: 	Sketch: 	
Monument Set (Procedures and Description): At the surveyed position along a line from the found corner common to sections 16, 17, 20 and 21 and the found west 1/16 corner common to Sections 17 and 20 set a 1/2"x30" galvanized iron pipe 15" in the ground surrounded by a mound of stones.		
New Accessories: A 1 1/2" Douglas Fir bears S 40°W 60 feet. Attached a bearing tree sign to the fir tree.		
Location & Comments: The corner is located on a steep Southeast slope in an area prone to rock slides.		Compass Declination: 19°East
Firm / Agency USKH Inc. Address: 5 N. Colville St. Walla Walla, WA 99362 Party Chief Damon Locke Notes Witness Levi Blackwolf		SURVEYOR'S SEAL 

08-112-C

6/30/08