


Index File No. V-25 **CORNER RECORD (SEARCH)** (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. _____
 T 3N R. 37E R.D. WALLA WALLA County UMATILLA
 Merid. WILLAMETTE N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found a stone 16x12x6 inches with no marks evident.
 Corner stone was in a mound of stone.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found a 14 inch diameter Douglas Fir snag N20°E, 10.9 feet with blaze evident.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner falls on the West slope approximately 90 feet East of a creek

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency Signature _____

Handwritten signature: Anna K. [unclear]

Title SURVEYOR Division _____ Headquarters _____ Date 9-6-91 FS-7100-52 (3/68)

1
2
3
4
5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 2½"x30" aluminum pipe with aluminum cap marked as shown:
 Pipe is set 26 inches in the ground.
 Raised a small mound of stone around monument.
 Buried the original corner stone South and alongside of monument.

	T3N	
R37E		R38E
S 25		S 31
<hr/>		
S 36		
1991		
OPLS 644		

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

New BTs:

A 14 inch diam. Douglas Fir bears N66°E, 43.61 feet marked X BT
 A 24 inch diam. Ponderosa Pine bears S69°E, 34.43 feet marked T3N R38E S31 BT
 A 12 inch diam. Douglas Fir bears S61°W, 13.84 feet marked T3N R37E S36 BT
 A 14 inch diam. Douglas Fir bears N64°W, 28.70 feet marked T3N R37E S25 BT
 Attached Bearing Tree and Land Survey Monument signs to the BTs
 Set a steel fencepost approximately 5 feet North with Land Survey Monument sign attached.

10

Work Done By D.I. Griffith Title Surveyor Date 7-01-91 State Registration No. OPLS 644
 or Agency

Certified Cor. Record Prepared ? Yes No Filed At: Umatilla Co. Surveyor Off. Date 10-91

11

REMARKS

Witnesses: Jeff Petersen and Jim Bennett

12

Index File No. V-25 T.3N R. 37E WM. Tract or Surv. No. Cor.

13

USDA-FOREST SERVICE

Index

File No. 4-25

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____


T 3N R. 37E

R.D. Walla Walla County Umatilla

Merid. Will

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Mound of stones at corner but none have any marks.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Orig. 10" fir is now 14" and alive with ~~sig~~ single healed blaze and bears N20°E, 14.5 ft from corner.

No trace of other 4 BT's found.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

Dennis L. Laybold

PLS 1636 S.O.

10-3-84

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.