

OREGON CORNER RESTORATION FORM

SECTION 23 TOWNSHIP 4 NORTH RANGE 29 EAST N-19
COUNTY : UMATILLA DATE 8-98

CORNER DESIGNATION

NORTH 1/4

CONDITION REPORT ONLY
 NOT FOUND
 RENEWED
 UNCOVERED
 SURVEYED IN
 REFERENCED

PREVIOUS RENEWALS / SURVEYS, ETC.


ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER CONTRACT #101. HE SET A POST IN A MOUND OF EARTH AND A CHARRED STAKE.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

NOTHING

SKETCH

MONUMENT DETAIL



MONUMENT SET (PROCEDURES AND DESCRIPTION)

ON A STRAIGHT LINE BETWEEN THE NE AND THE NW CORNERS AT THE CENTERLINE OF LOOP ROAD, I SET A 5/8" X 30" IRON REBAR WITH A 2" ALUMINUM CAP STAMPED AS ABOVE, FLUSH WITH THE PAVED SURFACE.

NEW ACCESSORIES FROM WHICH

AN ALUMINUM TAG #951 IN A POWER POLE LIES N 7°.04'00" E, 142.06 FEET.
AN ALUMINUM TAG #951 IN A 20" MAPLE TREE LIES N 49°.27'10" E, 32.14 FEET.
AN ALUMINUM TAG IN A 28" LOCUST TREE LIES 82°.50'00" E, 29.62 FEET.
A 5/8" X 30" IRON REBAR WITH PLASTIC CAP #951 LIES N 89°.56'22" W, 26.39 FEET.

LOCATION AND COMMENTS

COMPASS DEC.

SURVEYOR'S SEAL

FIRM/AGENCY
EDWARDS SURVEYING
P.O. BOX 763
HERMISTON, OREGON 97838
97838

PARTY CHIEF
D. EDWARDS

NOTES

WITNESS
RICK SMITH

RECEIVED BY
Umatilla County Surveyor
Date 10-98
Rec'd By RR
No. 98-213-C

REGISTERED
PROFESSIONAL
LAND SURVEYOR

G. Dennis Edwards

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951
RENEWS 12/31/99