

OREGON CORNER RESTORATION FORM

Section 33 Township 4 N Range 29 E

X-13

County UMATILLA Date 3/95

CORNER DESIGNATION

E 1/4 Cor

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals/Surveys, etc. ORIG SUR. DAVENPORT 1861 # 101
He set a post in mound with charred stake

Monument(s) & Accessories Found: (Condition and Source)

Nothing

Monument Detail

Sketch



Monument Set (Procedures and Description)

By single proportion I set 1" x 30" I. Pipe with
2 3/8" B.C. stamped as above 4" Below surface

SEE MY 1994-1 COUNTY PUBLIC MONUMENTATION SUR.

New Accessories

<u>Alum Tap in 22" ELM</u>	<u>Bears</u>	<u>S 75° 50' 20" W</u>	<u>37.78 FT.</u>
<u>" " " P. Pole</u>	<u>"</u>	<u>S 10° 34' 40" E</u>	<u>17.70 FT.</u>
<u>" " " 36" ELM</u>	<u>"</u>	<u>S 88° 12' 50" E</u>	<u>59.12 FT.</u>
<u>" " " P. Pole</u>	<u>"</u>	<u>N 6° 15' 30" E</u>	<u>145.76 FT.</u>

Location & Comments

@ Cor. of Stanfield Compass Declination _____
Loop Rd North & Firm/Agency EDWARDS
Stanfield Loop Rd West SURVEYING

Address P. Box 763

RECEIVED BY _____

HERMISTON, OR 97838

Umatilla County Surveyor _____

Party Chief D. EDWARDS

Date _____

Notes _____

Rec'd By _____

Witness J. COPPOCK

No. 95-60-B

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

J. Dennis Edwards

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951

RENEWS 12/31/95