

OREGON CORNER RESTORATION FORM

Section 23 Township 4N Range 30E

County UMATILLA Date 5/26/04

CORNER DESIGNATION

R-19
(SOUTH 1/4 CORNER)

- ___ Condition Report Only
- ___ Not Found
- ___ Renewed
- ___ Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals/Surveys, etc.:

DOLPHUS PAYNE, UNDER CONTRACT NO. 100, DATED AUGUST 1, 1861, SET CHARRED STAKE WITH MOUND, TRENCH, AND PITS.

Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail



Monument Set (Procedures and Description):

SET A 5/8" X 30" IRON REBAR WITH 1 1/4" YELLOW PLASTIC CAP MARKED AS SHOWN BY SINGLE PROPORTION BETWEEN THE SOUTHWEST AND SOUTHEAST CORNERS OF SECTION 23 WHICH WERE ALSO SET IN THIS SURVEY. MONUMENT IS APPROXIMATELY 4" BELOW THE SURFACE.

New Accessories:

- A 5/8" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "UCPWD...LS2627" BEARS N70°18'26"W, 105.94'.
- A 5/8" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "UCPWD...LS2627" BEARS S88°07'07"W, 234.43'.
- A 5/8" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "UCPWD...LS2627" BEARS S57°36'31"E, 13.37'.
- A 5/8" IRON REBAR WITH YELLOW PLASTIC CAP MARKED "UCPWD...LS2627" BEARS N81°49'47"E, 250.51'.

Location and Comments: Compass Declination: N/A


Surveyor's Seal

CORNER IS LOCATED IN THE GRAVEL SHOULDER NEAR THE SOUTH EDGE OF PAVEMENT OF DESPAIN GULCH ROAD APPROXIMATELY 6 MILES EAST OF ITS INTERSECTION WITH NORTH LOOP ROAD AND 1/2 MILE WEST OF ITS INTERSECTION WITH KILGORE ROAD.

Firm/Agency :
UMATILLA COUNTY
ROAD DEPARTMENT

Address:
3920 WESTGATE
PENDLETON, OREGON

Party Chief:
GARY ROBERTS
Notes:
GARY ROBERTS
Witness:
NONE



RENEWS 12/31/2004

04-121-C