

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 08/14/07

CORNER DESIGNATION: 4N31E, T-5. The West One-Quarter Corner of Section 29.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by W.H. Odell, under GLO Contract No. 114, dated July 2, 1866. Notes state: "Set post corner for 1/4 section, drove charred stake dug pits and raised mound as per instructions."

MONUMENT AND ACCESSORIES FOUND: Accepted ancient fence corner with fence and field lines extending East, West and South as best remaining evidence of original corner location.

MONUMENT MARKING DETAIL:

T4N R31E
S30|S29
2007
PLS 1106

MONUMENT SET:

At a point just North of accepted fence corner, set a 2 3/8" brass cap on 1 1/4 by 30" galvanized iron pipe. Brass cap projects 3" above ground.

New Accessories:

A 5/8" x 24" iron rebar with 1 1/4" red plastic cap marked "OR PLS 1106, WA PLS 17372", in fence line, bears North 87° East, 15.6 feet.

A 5/8" x 24" iron rebar with 1 1/4" red plastic cap marked "OR PLS 1106, WA PLS 17372", bears South 41° West, 13.0 feet.

A 5/8" x 24" iron rebar with 1 1/4" red plastic cap marked "OR PLS 1106, WA PLS 17372", bears North 90° West, 24.6 feet.

A 5/8" x 24" iron rebar with 1 1/4" red plastic cap marked "OR PLS 1106, WA PLS 17372", bears North 90° West, 52.0 feet.

Wired bearing object signs to each accessory rebar and nailed "Witness" sign to fence post South of corner monument.

LOCATION AND COMMENTS: Corner falls just North of fence corner post, with fences running East, West and South. See Umatilla County Partition Plat No. 2007-45 for additional survey reference information.

FIRM: William R. Wells, PLS
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Witnesses: Jason Wells, LSIT
Micah Engum

4N31T5

