

OREGON CORNER RESTORATION FORM

Section: 15
Township: 4N
Range: 37 EWM
County: Umatilla
Date: 05/23/00
Corner Designation: L-14, C-W 1/16 S 15

Previous Renewals/Surveys, etc.: None.

Monument(s) & Accessories Found (Condition & Source): None.

Monument Detail: T4N R37E
CW 1/16 S15
+
2000
LS 2820

Monument Set (Procedures & Description): At surveyed position, set a 1 1/2" x 30" galvanized iron pipe with a 2 1/2" brass cap 24" into the ground, surrounded with a mound of earth and stone.

New Accessories: Set 6' steel fence post 3' North of the corner with a Umatilla County land survey monument sign wired on it.

Set reference markers (R.M.), a 5/8" x30" rebar with a plastic yellow cap stamped "Tomkins Surveying". The R.M.s bear from corner as follows:

- N26° W, 15.25 feet with 6' steel fence posts along side with Umatilla County bearing object sign attached.
- N45°E, 10.75 feet with 6' steel fence posts along side with Umatilla County bearing object sign attached.
- S30°E, 14.20 feet with 6' steel fence posts along side with Umatilla County bearing object sign attached.
- S38°W, 12.90 feet with 6' steel fence posts along side with Umatilla County bearing object sign attached.

Location & Comments: The corner is located on an open East sloping spur ridge 60' ± South of the edge of the timber.

Compass Declination:
19° East

Firm/Agency: Tomkins Land Surveying, Inc.
20 E. Poplar, Suite 204
Walla Walla WA 99362

Party Chief: Thomas Butler
Notes: Thomas Butler
Witness: Ryan Laughery

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Greg E. Flowers
OREGON
JUNE 30, 1997
GREG E. FLOWERS
02820LS

RENEWS 12/31/01

12/15/00

RECEIVED BY
Umatilla County Surveyor
Date *12-00*
Rec'd By *SM*
No. *00-758-C*