

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 4N, R 37E., W.M.

Corner Code No. V-13

Note: Monument marked as shown below


History of original corner establishment:

This corner was originally established by George S. Pershin, U.S. Deputy Surveyor, under Contract No. 322, dated July 29, 1879.

The original notes state:

Set fir post on Northwest slope for corner to sections 27, 28, 33, & 34 from which:

- A fir 20 in. dia. bears N 12° E, 50 links.
- A fir 8 in. dia. bears S 8° E, 32 links.
- A fir 18 in. dia. bears S 48° W, 30 links.
- A spruce 14 in. dia. bears N 12° W, 17 links.



Corner No.
Compass Declination: 18°

Description of corner evidence found:

Found a 2 1/2" brass cap on a 1 1/4" galvanized iron pipe protruding 6" out of ground from which:

- A 8" dead white fir snag bears N 34° W, 11.8' with scribes visible.
- A 10" dying white fir bears N 41° E, 19.5' with scribes visible on a partly healed blaze.
- A 7" Pacific yew bears S 30° W, 23.0' with scribes visible.

Description of monument and accessories I established to perpetuate the original location of this corner:

Marked 3 new bearing trees: (no nearby trees in NE quad, or NW quad)

- A 11" Englemann spruce bears S 35° E, 22.3', scribed T4N R37E S34 BT.
- A 11" Englemann spruce bears S 17 1/2° E, 27.3', scribed T4N R37E S34 BT.
- A 6" Pacific yew bears S 76° W, 27.3', scribed T4N R37E S33 BT.

Put bearing object signs on all bearing trees.

Set steel fence post South of corner with a witness corner sign attached.

Mounded monument with earth.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19....

..... by

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

Date 9-91

Rec'd By ER

No. 91-25-C