

USDA-FOREST SERVICE

Index File No. L-18

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. _____

T 4 S R. 30E

R.D. Ukiah

County Umatilla

Merid. Willamette

N.F. Umatilla

State Oregon

CORNER DIAGRAM

T45 R30E

W 1/16

C — C

S 14

1981

PLS 848



DESCRIBE CORNER MONUMENT FOUND

Corner not previously established.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N/A

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is on a North slope in heavy fir timber, approx. 80 ft. in elev. below open ridge top. An old trail runs along ridge top approx. 250 ft. South of corner.

Signature

Title

Division

Headquarters

Date

PLS 848

Mt. Vernon, OR

7/31/81

7100-52-(3-68)

8

2

3

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram, set 20" in the ground.

From which:

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A fir 9 in. dia. bears N24°E, 21.4 ft. scribed CW 1/16 S 14 BT.
A fir 8 in. dia. bears S25° E, 15.3 ft. scribed CW 1/16 S 14 BT.
Set steel posts with warning and boundary signs 5 ft. West and 5 ft. North from corner.
Nailed bearing tree signs and brass washers stamped PLS 848 to each tree.
Painted red band around each tree.

Work Done By D.M. Ferguson Title Surveyor Date 7/31/81 State Registration No. OR PLS 848 or Agency

Certified Cor. Record Prepared Yes No Filed At: Matilla Co. Surv. Office Date 10/81

PROFESSIONAL
LAND SURVEYOR

REMARKS

Witnesses to above corner:

D. Mitchell Ferguson
Mike Woodward

OREGON
JULY 12, 1966
DOUGLAS M. FERGUSON
848