


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



1-23

Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram. Set pipe 20 inches in the ground and placed a ring of stone around the pipe.

From which:

A pine 8 inches dia. bears N21°E, 22.0 ft. scribed C 1/4 S 13 BT.

A pine 10 inches dia. bears S 82°W, 15.7 ft. scribed C 1/4 S 13 BT.

Set steel posts with warning and boundary signs 5 ft. North and 5 ft. East from corner.

Nailed bearing tree signs and brass washers stamped PLS 848 to each tree. Painted red band around each tree.

I hereby certify that the above corner monument was established as herein described on 8/6/81.

Witnesses:

D. Mitchell Ferguson

Mike Woodward

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Douglas M. Ferguson*  
OREGON  
JULY 12, 1968  
DOUGLAS M. FERGUSON  
848

Office of... Co. Surveyor..... County of... Umatilla  
Oregon  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the... 15... day of... January....., 1982  
... *David Truman*... by *Betty Shatt*  
(COUNTY OFFICIAL) (DEPUTY)

82-1-C

T-2