

USDA-FOREST SERVICE

Index File No. M-18

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T T4S R. 30E

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



T4S R30E
SW 1/16 S 14
1981
PLS 848

DESCRIBE CORNER MONUMENT FOUND

Corner not previously established.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N/A

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is on a North slope approx. 150 ft. Mor. South from draw bottom and 400 ft. South from road jct. Road to NE and SE.

Signature

Title PLS 848 Division _____ Headquarters Mt. Vernon, OR Date 8/12/81
7100-52-(3,68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" galv. iron pipe with 3" brass cap, stamped as shown on the diagram, set 25 in. in the ground.
A 6 inch fir south alongside pipe is scribed SW 1/16 S 14.

From which:

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A tamarack 16 in. dia. bears N50°E, 45.4 ft. scribed SW 1/16 S 14 BT.
A fir 11 in. dia. bears S70°E, 6.0 ft. scribed SW 1/16 S 14 BT.
Set steel posts with warning and boundary signs 5 ft. South and 5 ft. East from corner.
Nailed bearing tree signs and brass washers stamped PLS 848 to each tree.
Painted a red band around each tree.

Work Done By D.M. Ferguson Title Surveyor Date 8/12/81 State Registration No. OR PLS 848
or Agency

Certified Cor Record Prepared? Yes No Filed At: Umatilla Co. Surv. Office Date 10/81

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

REMARKS

Douglas M. Ferguson
**OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848**