


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



Q-24-

Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram. Set pipe 14 inches in the ground and raised a mound of stone around pipe.

From which:

A pine 11 inches dia. bears N56°W, 42.2 ft. scribed SE 1/16 S 24 BT.
A pine 11 inches dia. bears S20°E, 67.4 ft. scribed SE 1/16 S 24 BT.
Set steel posts with warning and boundary signs 5 ft. East and 5 ft. North from corner.
Nailed bearing tree signs and brass washers stamped PLS 848 to each tree.
Painted red band around each tree.

I hereby certify that the above corner monument was established as herein described, on 8/13/81.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
JULY 12, 1969
DOUGLAS M. FERGUSON
848

Witnesses: D. Mitchell Ferguson

Mike Woodward

Office of Co. Surveyor County of Umatilla

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the 25 day of January, 1982

David K. Hixon by Betty J. Hixon

(COUNTY OFFICIAL)

(DEPUTY)

82-01-C

T-2