


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



R-22

Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram, set 6 inches in the ground and raised a mound of stone around pipe.

No bearing trees available.  
Set steel posts with warning and boundary signs 5 ft. North and 5 ft. West from corner.

I hereby certify that the above corner was established as herein described on 7/2/81.

Witnesses to above corner:

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1905  
DOUGLAS M. FERGUSON  
848

\_\_\_\_\_  
D. Mitchell Ferguson

\_\_\_\_\_  
Dave Herburger

Office of..... Co. Surveyor..... County of..... Umatilla  
State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the... 7<sup>th</sup> day of... January....., 19... 81  
..... David H. Sumner..... by Billy Thall.....  
(COUNTY OFFICIAL) (DEPUTY)

82-001-8