


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



U-24

Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram. Set pipe 24 inches in the ground.

From which:

A lodge pole pine 9 inches dia. bears N1°E, 30.6 ft. scribed SE 1/16 S 25 BT.

A fir 8 inches dia. bears S11°E, 8.2 ft. scribed SE 1/16 S 25 BT.

Set steel posts with warning and boundary signs 5 ft. South and 5 ft. East from corner.

Nailed bearing tree signs and brass washers stamped PLS 848 to each tree.

Painted red band around each tree.

I hereby certify that the above corner monument was established as herein described on 7/29/81.

Witnesses: Douglas Mitchell Ferguson

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Douglas M. Ferguson
OREGON
JULY 12, 1965
DOUGLAS M. FERGUSON
848

Mike Woodward

Office of... Co. Surveyor... County of... Umatilla...
State of... Oregon... I hereby certify that the within instrument was filed in this office
for record on the... 7th day of... January... 1982
... David K. ... by Betty ...
(COUNTY OFFICIAL) (DEPUTY)

82-01-C

T-2