


Index File No. ~~119~~
T 4S R. 30E
Merid. Willamette

CORNER RECORD (SEARCH) Tract or Survey No.
R.D. Ukiah County Umatilla
N.F. Umatilla State Oregon

Cor. No. 22 / X-9

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND *Original notes*
skid trail plowed out corner
BT PP 28" DBH N82W, 73 lks, has form 448
other BT has fallen over with scribing illegible.
Monumented By BLM, 1978

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
Sec. Line Board on Road S518 thus North (1/4 corner is east about 250-300' of this line)

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature: *15/Walton A. Young* Title: *For Tech.* Division: _____ Headquarters: _____ Date: *4-8-63*
7100-52 REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes . No Filed At: _____ Date _____

11

REMARKS

12

Index File No. X-9 T. R. M. Tract or Surv. No. Cor, _____

13