

USDA-FOREST SERVICE


Index
File No. L-6
T 4S R. 32E
Merid. W.M.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor. CW1/16
No. _____
R.D. Ukiah County Umatilla
N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None Set.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None Set

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner falls on steep east slope, about 50 feet west of small drain .

Barney B Barbour
Signature

Title
P.L.S.

Division

Headquarters

Date

11/4/77

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

GPO 902-673

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

T4S R32E

At surveyed point set 2½"x30" galvanized pipe with brass cap marked: W1/16C—+—C S17
 Set pipe 22" in the ground with mound of stone around.

OR PLS 1051
1977

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

From which: A Tamarac 21" in dia. bears N13°E, 3.0', scribed W C1/16 S17 BT.
 A Fir 12" in dia. bears S57°W, 34.9', scribed W C1/16 S17 BT.
 Placed 54-3s and 54-4s on trees, brass washer on BT blazes stamped PLS 1051.
 Painted 6" red band around BT's and painted both blazes red. Placed 54-2,
 54-4, and 54-9 on fence post 4' south of corner.

10

Work Done By B.B. Barbour Title P.L.S. Date 11/4/77 State Registration No. or Agency OR PLS 1051

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

Witnesses: D.L. Landers
 S. Nelson

12

Index File No. _____ T. _____ R. _____ M. _____ Tract or Surv. No. _____ Cor. _____

13