

USDA-FOREST SERVICE


Index
 File No. N-8
 T 4S R. 32E
 Merid. W.M.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)
 R.D. Ukiah County Umatilla
 N.F. Umatilla State Oregon

Tract or
 Survey No. Cor. No. E1/16

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None Set.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None Set.

PHOTO IDENTIFICATION DATA

Photo No.
 Filed At.
 Object Ident.
 Ident. By
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

The corner lies on a steep southeast slope about 150 feet west of bottom of gully with small stream and about 20 feet west of north-south fence.

PLANE COORDINATE POSITION DATA

State Zone
 X
 Y
 Estab. By
Agency

Barry B Barbour

Title P.L.S. Division Headquarters Date 11/10/77
 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

GPO 902-673

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

T4S R32E

Set a 2½"x30" galvanized pipe with brass cap marked:

S17

Set pipe 18" in ground and built mound of stone to cap.

E1/16 ———
 |

S20

1977

OR PLS 1051 9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A Fir 10" in dia. bears N80W, 21.0 ft., scribed E1/16 S17 BT. A Fir 14" in dia. bears S100W, 54.0 ft., scribed E1/16 S20 BT. Attached brass washer, stamped PLS 1051, to each BT. Attached a 54-3 and a 54-4 sign to each BT. Set a painted metal fence post 4 ft. north of monument with a 54-2 and a 54-9 sign attached. Set another post 2 ft. west of monument with a 54-2 and a 54-4 sign attached. Painted a 6" band around each BT and both blazes on each BT red.

10

Work Done By R. C. Orton Title Party Chief Date 11/10/77 State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Witnesses: G. Wagoner,
 L. Clemens

12

Index-File No. _____ T. _____ R. _____ M. _____ Tract or Surv. No. _____ Cor. _____

13