

USDA FOREST SERVICE

CORNER RECORD (SEARCH)

Index

File No. P-20

R.D.: N.F.J.D.

Co. Survey No:

T.4S., R.32E.

N.F.: UMATILLA

County: Umatilla

Meridian: Willamette

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

T4S R32E

E1/16

None. Corner established this survey.

C-----C

823

1994

PLS 2405

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO ID DATA

None. Corner established this survey.

Photo No.

Filed At

Object ID

PLANE CO-ORD

State Zone

X


Y

DESCRIBE CORNER LOCATION:

Estab. By

Corner falls on east slope of D. Fir and P. Pine.. E-W
fence is 25' north.

Signature:



Title: Land Surveyor

Date: 11/2/94

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON.
Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the DIAGRAM, 26" in the ground.
From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE
Douglas Fir, 18" dia., bears N32°42'W, 53.5 ft., scribed: C-E1/16 S23 BT
Douglas Fir, 12" dia., bears S26°28'W, 23.8 ft., scribed: C-E1/16 S23 BT
Measurements to BT's taken with an Electronic Tacheometer with bearings
based on the survey control network. Set steel fence post with Land Survey
Monument (54-9) and Property Boundary (54-2) signs 5' north and south of
the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT
scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze
and Land Survey Monument (54-9) signs on back of each tree as required.
Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Dr. Land Surveyor No. 2405 Date: 11/2/94
Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co. Survey.

REMARKS

Index File No. P-20 T.4S., R.32E., W.M.