


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Q-17

History of original corner establishment:

None. Corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by survey...

Set a 2 1/2"x30" aluminum pipe with 2 1/2" aluminum cap 24" in ground surrounded with mound of earth and stone set steel fence post North of corner and attached signs 54-2 & 54-9. Cap marked as shown in corner diagram.

New bearing trees established:

A 11" ponderosa pine brs S14 1/2° E, 99.6' scribed S1/16S23 BT.

A 10" ponderosa pine brs' N58 1/2° W, 62.1' scribed S1/16S22 BT.

New BT's have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 18° East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on June 05, 1992.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 7, 1977
WILLIAM R. WELLS
1106

Office of County Surveyor County of Umatilla

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the day of , 19.....

..... by

(COUNTY OFFICIAL)

(DEPUTY)

RECEIVED BY

Umatilla County Surveyor

Date 7-97

Rec'd By AK

No. 92-803

Q-17

Form R6-7100-57 (9/71)

★ GPO-798-276