

USDA FOREST SERVICE

CORNER RECORD (SEARCH)

Index

File No. Q-24

R.D.: N.F.J.D.

Co. Survey No:

T.4S., R.32E.

N.F.: UMATILLA

County: Umatilla

Meridian: Willamette

CORNER DIAGRAM | DESCRIBE CORNER MONUMENT FOUND

T4S R32E

SE1/16

| None. Corner established this survey.

•
S24

1994

PLS 2405

| DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

| None. Corner established this survey.

PHOTO ID DATA

Photo No.

Filed At

Object ID

PLANE CO-ORD

State Zone

X


Y

| DESCRIBE CORNER LOCATION:

Estab.By

| Corner falls on slope of P.Pine and D.Fir. E-W road is
| 100 ft. south. E-W fence 120 ft. south.

Signature:



Title: Land Surveyor

Date: 10/18/94

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON.
Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the DIAGRAM, 24" in the ground.

From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE
Ponderosa Pine, 18" dia., bears N31°49'E, 20.9 ft., scribed: SE1/16 S24 BT
Ponderosa Pine, 14" dia., bears S51°11'E, 59.1 ft., scribed: SE1/16 S24 BT
Measurements to BT's taken with an Electronic Tacheometer with bearings
based on the survey control network. Set steel fence post with Land Survey
Monument (54-9) and Property Boundary (54-2) signs 5' north and west of the
monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe
as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and
Land Survey Monument (54-9) signs on back of each tree as required.
Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Dr. Land Surveyor No. 2405 Date: 10/18/94
Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co. Survey.

REMARKS

Index File No. Q-24

T.4S., R.32E., W.M.