

USDA FOREST SERVICE

CORNER RECORD (SEARCH)

Index

File No. R-18

R.D.: N.F.J.D.

Co. Survey No:

T.4S., R.32E.

N.F.: UMATILLA

County: Umatilla

Meridian: Willamette

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

T4S R32E

S23

None. Corner established this survey.

W1/16—

S26

1994

PLS 2405

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None. Corner established this survey.

PHOTO ID DATA

Photo No.

Filed At

Object ID

Plane CO-ORD

X

Y

Estab.By

DESCRIBE CORNER LOCATION:

Corner falls on north slope of larch and fir. E-W draw bottom is 100 ft. north. Old E-W road is 150 ft. north.

Signature:

Title: Land Surveyor Date: 11/1/94

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON.  
Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown  
on the DIAGRAM, 26" in the ground.

From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE Western  
Larch, 11" dia., bears N18°12'E, 6.5 ft., scribed: W1/16 S23 BT  
Douglas Fir, 12" dia., bears S77°18'E, 61.0 ft., scribed: W1/16 S26 BT  
Measurements to BT's taken with an Electronic Tacheometer with bearings based on  
the survey control network. Set steel fence post with Land Survey Monument  
(54-9) and Property Boundary (54-2) signs 5' south and west of the monument.  
Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this  
survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument  
(54-9) signs on back of each tree as required. Painted a 6" red band above  
Bearing Trees signs.

Work Done by: Susan E. Newstetter Or. Land Surveyor No. 2405 Date: 11/1/94  
Certified Cor. Record Prepared?  Yes  No Filed At: Umatilla Co. Survey.

REMARKS

Index File No. R-18

T.4S., R.32E., W.M.