

USDA FOREST SERVICE
Index

CORNER RECORD (SEARCH)

File No. S-20
T.4S., R.32E.

R.D.: N.F.J.D.
N.F.: UMATILLA

Co. Survey No:
County: Umatilla

Meridian: Willamette

CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
T4S R32E NE1/16 • S26 1994 PLS 2405	None. Corner established this survey.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
None. Corner established this survey.

PHOTO ID DATA
Photo No.
Filed At
Object ID

PLANE CO-ORD
State Zone

X
Y

Estab.By

DESCRIBE CORNER LOCATION:
Corner falls on north slope of L.P. Pine and W. Larch.

Signature:



Title: Land Surveyor

Date: 10/26/94

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON.
Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the DIAGRAM, 27" in the ground.

From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE
Western Larch, 10" dia., bears N22°12'W, 21.5 ft., scribed: NE1/16 S26 BT
Lodgepole Pine, 14" dia., bears S04°20'W, 69.1 ft., scribed: NE1/16 S26 BT
Measurements to BT's taken with an Electronic Tacheometer with bearings
based on the survey control network. Set steel fence post with Land Survey
Monument (54-9) and Property Boundary (54-2) signs 5' north and west of the
monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe
as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and
Land Survey Monument (54-9) signs on back of each tree as required.
Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Dr. Land Surveyor No. 2405 Date: 10/26/94
Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co. Survey.

REMARKS

Index File No. S-20

T.4S., R.32E., W.M.