

## USDA FOREST SERVICE

## CORNER RECORD (SEARCH)

Index

File No. T-17

R.D.: N.F.J.D.

Co. Survey No:

T.4S., R.32E.

N.F.: UMATILLA

County: Umatilla

Meridian: Willamette

## CORNER DIAGRAM

## DESCRIBE CORNER MONUMENT FOUND

T4S R32E

Found 18"x12"x4" stone, marked 1/4, in the bottom of a rock jack. Accepted as the original position.

1/4

S271S26

1994

PLS 2405

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None originally set, none found.

## PHOTO ID DATA

Photo No.

Filed At

Object ID

## PLANE CO-ORD

State Zone

X

Y

## DESCRIBE CORNER LOCATION:

Estab.By

Corner falls on north side of E-W ridgetop. A N-S fence is 2' east. Old E-W road is 70 ft. north.

Signature:

*Aue Hewitler*

Title: Land Surveyor

Date: 11/1/94

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON.  
Moving the original corner stone aside I set in it's place a 2-1/2"x30"  
aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 14"  
in the ground and raised a mound of earth and stone around the monument.  
The original stone is alongside the monument on the north side. From  
Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE  
Ponderosa Pine, 12" dia., bears N64°30'E, 108.4 ft., scribed: 1/4 S26 BT  
Ponderosa Pine, 16" dia., bears S52°15'E, 132.4 ft., scribed: 1/4 S26 BT  
5/8"x30" rebar, with yellow plastic cap marked PLS 2405, bears:  
N47°15'W, 12.1 ft. (no grooves on rebar)  
S46°00'W, 11.9 ft. (1 groove on rebar)  
Measurements to BT's and rebar taken with a magnetic compass, declination  
20° East, and a nylon clad steel tape. Set steel fence post with Land  
Survey Monument (54-9) and Property Boundary (54-2) signs 5' north of the  
monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe  
as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and  
Land Survey Monument (54-9) signs on back of each tree as required.  
Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Dr. Land Surveyor No. 2405 Date: 11/1/94  
Certified Cor. Record Prepared?  Yes  No Filed At: Umatilla Co. Survey.

Index File No. T-17

T.4S., R.32E., W.M.