

USDA FOREST SERVICE  
Index

CORNER RECORD (SEARCH)

File No. T-24  
T.4S., R.32E.  
Meridian: Willamette

R.D.: N.F.J.D.  
N.F.: UMATILLA

Co. Survey No:  
County: Umatilla

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

T4S R32E

E1/16

C-----C

S25

1994

PLS 2405

None. Corner established this survey.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None. Corner established this survey.

PHOTO ID DATA

Photo No.

Filed At

Object ID

PLANE CO-ORD

State Zone

X


Y

Estab. By

DESCRIBE CORNER LOCATION:

Corner falls on north slope of white fir and western  
larch.

Signature



Title: Land Surveyor

Date: 10/24/94

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MON.  
Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown  
on the DIAGRAM, 26" in the ground.

From Which:

ACCESSORIES: DESCRIBE NEW BT'S, W.O.'S ETC. ESTABL./WORK DONE TO PRESERVE  
Western Larch, 24" dia., bears N81°30'E, 43.6 ft., scribed: C-E1/16 S25 BT  
White Fir, 11" dia., bears S48°00'W, 18.9 ft., scribed: C-E1/16 S25 BT  
Measurements to BT's taken with a magnetic compass, declination 20° East,  
and a nylon clad steel tape. Set steel fence post with Land Survey  
Monument (54-9) and Property Boundary (54-2) signs 5' south and west of the  
monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe  
as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and  
Land Survey Monument (54-9) signs on back of each tree as required.  
Painted a 6" red band above Bearing Trees signs.

Work Done by: Susan E. Newstetter Or. Land Surveyor No. 2405 Date: 10/24/94  
Certified Cor. Record Prepared?  Yes  No Filed At: Umatilla Co. Survey.

REMARKS

Index File No. T-24

T.4S., R.32E., W.M.