

Index File No. R-5

CORNER RECORD (SEARCH)

Tract or Survey No. _____ Cor. No. _____

T 5 S. R. 30 E


R.D. UKIAH County Umatilla

Merid. Will.

N.F. Umatilla State Ore.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



Monumented By BLM, 1978

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

12" D.B.H. Pine brs. N. 70° E. 40 lks. - Good vigor
 32" D.B.H. Pine brs. S. 41° W. 129 lks. - Good vigor
 22" D.B.H. Pine brs. N. 75° W. 155 lks. - Good vigor

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Don McCullough

Title

Forestry Tech.

Division

Headquarters

UKIAH

Date

8-31-66

7100-52

REV. '65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. *R-5* T. R. M. Tract or Surv. No. Cor. 12
13