

USDA-FOREST SERVICE

Index

File No. Z-15

T5S R30E

Merid. Willamette

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

R.D. North Fork John Day

N.F. Umatilla

Tract or

Survey No

County Umatilla

State Oregon

Cor.

No.

x

Corner Diagram

T5S R30E

1/4 S34

T6S R30E

1976

9PLS 598

1

1 Describe corner monument found

1 Steel pipe extending 8" above the ground with a 2 1/2" brass cap stamped as shown in the diagram. The monument was in a small stone mound.

1

1

1

x

Photo Identification Data

Photo No.

filed at

Object Ident.

Ident. by

Signature

1

1 Describe bearing trees or other official accessories found

1 The remains of a fir stump bear N51 W, 9.9', with a Forest Service Bearing Tree sign attached.

1 A 22" Ponderosa Pine bears N53°E, 48.0' with healed scribe.

1 A 16" Western Larch bears N74°W, 35.1' with healed scribe.

1

x

Plane Coordinate Position Data

State

Zone

X

Y

Estab. by

Agency

1

1 Describe corner location relative to near-by features, also how to reach corner

1 From the junction of roads 5312 and 5320, follow 5320 east 1.6 miles to road 5320110. Then follow road 5320110 east 0.5 miles to road 5320130. Follow road 5320130 south 0.4 miles to an east-west fence line. Follow the fence east approximately 500' to a draw. The corner is 70' west of this draw and 6' north of the fence.

x

Signature

David L. Hadlock

Title

Land Surveyor

Division

Headquarters

Pendleton, OR

Date

June 1988

7100.52

CORNER RECORD (PERPETUATION)

X \_\_\_\_\_ X  
Monument: Describe new monument set, or work done to preserve existing monument

None

x \_\_\_\_\_ x  
Accessories: Describe new BT's witness objects etc. established, or work done to preserve existing evidence

None

x \_\_\_\_\_ x  
Work done by David L. Haddock Title Land Surveyer Date State Registration No.  
Certified cor. record prepared? yes no x Filed at or Agency 852  
Date

x \_\_\_\_\_ x  
REMARKS

x \_\_\_\_\_ x  
Index File No. Z-15 T.5S. R.30E. M. Willamette Tract or Survey No Cor.

USDA-FOREST SERVICE

Index

File No. Z-15

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. \_\_\_\_\_

Cor. No. 14

Z-15

T 55 R. 30E

R.D. UKIAH County UMATILLA

Merid. \_\_\_\_\_ N.F. UMATILLA State OR

CORNER DIAGRAM



T55R30E  
1/4 534

DESCRIBE CORNER MONUMENT FOUND

FOUND BASALT STONE 12X8X5 DIMLY MKD 1/4

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

REMAINS OF 8" FIR STUMP BR S NS10W 9.9 FT. BLAZE MKD 1/4 S BT WAS ALONGSIDE STUMP.

REMAINS OF FIR BR S 80W 15 FT

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

COR IS 6' N. OF E-W FENCE & 70 W. OF DRY CREEK BED

Signature

RD Brissett

Title

LANDSURVEYOR

Division

Headquarters

Date

9-30-76

7100-52-(3/68)

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 2 1/2" X 30" IRON PIPE MKD  
 RAISED MOUND OF STONE TO TOP OF PIPE.

T55R30E  
 1/4 534  
 T65R30E  
 1976  
 OPL5598

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

NEW BT'S:

A 22" PINE BRS N53°E 48° FT. MKD T55R30E 1/4 534 SC BT.  
 A 16" TAMARACK BRS N74°W 35! FT. " T55R30E 1/4 534 SC BT.

10

Work Done By R. D. BAGETT Title LAND SURVEYOR Date 9-30-76 State Registration No. OPL5 598  
 or Agency

Certified Cor. Record Prepared? Yes  No Filed At: UMATILLA OS Date

11

REMARKS

12

Index File No. 2-15 T.

R.

M.

Tract or Surv. No.

Cor.

13