

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 08/28/02

CORNER DESIGNATION: E-21, The Northeast Corner of Section 11, T5S, R31E, W.M..

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by George S. Pershin, under Contract No. 373, dated September 17, 1880. Notes state: Set pine post on level for cor. to Sec. 1, 2, 11 & 12. A pine, 20 ins. diam. brs. N 17° E., 53 lks. Dist., a pine, 22 ins. diam. brs. S 75° E., 49 lks. dist., a pine, 15" diam. brs. S 60° W., 63 lks. dist., a pine, 10 ins. diam. brs. N 63° W., 67 lks. dist.

MONUMENT AND ACCESSORIES FOUND: Found root hole of SW BT with uprooted stub of tree lying nearby, bears S 60° W., 44.2 feet. No trace of other bearing trees. The corner area has been logged and cleared for a gate and fence building. There are indications of an old road bed extending South from the corner area. Corner falls at a turn in County Road No. 1447 and fits the County Road extending West and North, in conformance with original County Road survey notes, (road notes state the survey of the portion of County Road No. 1447 extending West began 20 feet South of the corner and that position lines up with the road centerline extending West). There was a USFS bearing tree tag on a 32" ponderosa pine bearing N 65° W., 67.3 feet from corner. We cut into the tree and find no evidence of a blaze face. The tree has a fence build through it and there is evidence of scarring from fence construction.

MONUMENT MARKING DETAIL:

T5S R31E
S2 | S1
S11 | S12
2002
PLS 1106

MONUMENT SET:

At a point N 60° E., 44.2' from SW bearing tree remains, set a 2 1/2" brass cap on a 1 1/4" x 30" galvanized iron pipe with cap 3" above ground level in a small mound of stone. Monument cap marked as shown in "Monument Marking Detail".

New Accessories:

A 3/4" Brass washer stamped "PLS 1106" 1 foot above ground level nailed to a rail road tie gate post bears N 73° E, 39.8 feet.

A 26" diam. ponderosa pine scribed "T5S R31E S12 BT" with a 3/4" brass washer stamped "PLS 1106" nailed to the blaze bears S 44° E, 109.0 feet.

A 10" diam. ponderosa pine scribed "T5S R31E S11 BT" with a 3/4" brass washer stamped "PLS 1106" nailed to the blaze bears S 50° W, 148.2 feet.

A 32" diam. ponderosa pine bears N 65° W, 67.3 feet. This tree was opened with a chain saw in searching for the corner and has a 6" by 5" by 16" wedge cut from it.

Attached bearing object signs to accessories. Attached witness sign to rail road tie gate post, North of the corner.

LOCATION AND COMMENTS:

Corner falls at projection of the center of County Road No. 1447 extending North and the North edge of County Road No. 1447 extending West. Corner located 4 feet South of fence on South side of road.

FIRM: William R. Wells, PLS
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells, LSIT
Mark Hammersla

VS31E21

RECEIVED BY
Umatilla County Surveyor
Date 10-02
Rec'd By KR
No. 02-218-B

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-04