

Index
File No. L-25

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. _____T 5 S. R. 30 E.R.D. Ukiah


County

UmatillaMerid. WillametteN.F. Umatilla

State

Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Stone mound; mound 4' diam., 1' deep; 1' above ground; fair condition.

Mound is exactly ~~in~~ north-south fence line. Could not identify $\frac{1}{4}$ corner stone.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A location poster dated 1946 on a 10" ponderosa pine bears SW approx. 12'. Tree has old blazes. May be B.T. but probably too young for original.

A 10" Ponderosa pine bears N. 64°W., approx. 25'. It has a brand on it 14" high and 7' wide which appears to be R

3

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner sets in north-south fence line. There is a primitive road about 600' N.W. (Sugarbowl 7.5 minute quadrangle map shows old road as Jeep Trail.)

4

6 PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

T, Hollamon

Eng, Tech,

Z S,O,

4/19/74

5

T

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

I placed a location poster on gate post in line fence about
900 ft. north.

10

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

12

13