

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 08/01/02

CORNER DESIGNATION: N-21, The Southeast Corner of Section 14, T5S., R31E., W.M.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally set by George S. Pershin, under Contract No. 373, dated Sept. 17, 1880. Notes state: Set pine post 6" square and 4' long in moist loamy bottom prairie for corner to Section 13,14,23 and 24. No accessories.

MONUMENT AND ACCESSORIES FOUND: None. Original notes actually indicate this corner would not last long because of cattle.

MONUMENT MARKING DETAIL:

T5S R31E
S14 | S13
S23 | S24
2002
PLS 1106

MONUMENT SET:

Reestablished corner by double proportion measurement between the recovered NE Corner of Section 14, the recovered East 1/4 Corner of Section 23, the recovered South 1/4 Corner of Section 14 and the recovered South 1/4 Corner of Section 13. At position determined by survey, set a 2 1/2" brass cap on a 1 1/4" x 30" galvanized iron pipe with top of cap flush with ground in a large marshy meadow. Monument marked as shown in "Monument Marking Detail". The corner accessories are all west of the monument where a fence and field road exist.

New Accessories:

A 5/8" x 24" iron rebar with a yellow plastic cap marked "OR PLS 1106, WA PLS 17372", 2" above ground in a wire fence running along a field road bears S 45 1/2° W, 133.4 feet.

The top center of the east side of a 24" diameter CMP culvert under a field road bears S 84° W, 118.9 feet.

A 3/4" brass washer stamped "PLS 1106" nailed to a wood fence post rock crib 1 foot above ground bears N 64° W, 108.1 feet.

A 5/8" x 24" iron rebar with a yellow plastic cap marked "OR PLS 1106, WA PLS 17372", 2" above ground in a wire fence running along a field road bears N 41° W, 162.0 feet.

Attached bearing object signs to all accessories other than the culvert. Set a steel fence post with a witness post sign wired to it 1 foot North of the corner.

LOCATION AND COMMENTS: Corner is located in a wet marshy meadow approximately 100 feet East of a N-S farm road.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD 83/91, INT. FOOT:

N = 536300.84
E = 8609507.48

FIRM: William R. Wells, PLS
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Witnesses: Jason Wells, LSIT
Mark Hammersla
5S31N21

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-04

RECEIVED BY

Umatilla County Surveyor

Date 10-02

Rec'd By KF

No. 02-218-B