

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 08/22/02

CORNER DESIGNATION: J-25, The Northeast Corner of Section 13, T5S, R31E, W.M..

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by George S. Pershin, under Contract No. 362, dated August 2, 1880. Notes state: Set basalt stone, 18 x 10 x 7, on level, in mound of stone, on level for corner to Sec. 12, 13, 7 & 18. A pine, 8 ins. diam., brs. N 4° W., 362 lks. dist. No other trees.

MONUMENT AND ACCESSORIES FOUND:
Found original bearing tree, now 16", which was opened to reveal scribing. Fences have been constructed in corner area. The original stone and mound were not found.

MONUMENT MARKING DETAIL:

T5S
R31E R32E
S12|S7
S13|S18
2002
PLS 1106

MONUMENT SET:

Reestablished corner position S 04° E., 362 lks (238.9 feet) from face of original bearing tree. At reestablished corner position, set a 2 1/2" brass cap on a 1 1/2" x 30" galvanized iron pipe 24" in the ground. Built a mound of earth and stone around corner monument. Cap is marked as shown in "Monument Marking Detail". The reestablished corner point falls 1 foot South of old East-West fence. There are remains of an old fence extending South from the Corner.

New Accessories:

- A 3/4" brass washer stamped "PLS 1106", 1 foot above ground in a wood post at a rock jack bears N 87° W, 110.6 feet.
- Center of a mound of stone from in an existing rock jack in a creek bed bears N 87° W, 56.7 feet.
- A 3/4" brass washer stamped "PLS 1106", 1 foot above ground in a wood post at rock jack bears N 86° W, 17.3 feet.
- A 3/4" brass washer stamped "PLS 1106", 1 foot above ground in a wood post at rock jack bears N 86° E, 12.2 feet.
- A 3/4" brass washer stamped "PLS 1106", 1 foot above ground in a wood post at rock jack bears East, 122.8 feet.

Attached bearing object signs to all accessories except stone mound in rock jack in creek bed.

LOCATION AND COMMENTS: Corner falls 1 foot South of old East-West fence. There are remains of and old fence extending South from the Corner. There is a large pile of rocks from an old rock crib just North of the fence line North of the Corner.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD 83/91, INT. FOOT:
Not observed.

FIRM: William R. Wells, PLS
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East Surveyor's Seal

Witnesses: Jason Wells, LSIT
Mark Hammersla

5S31J25

RECEIVED BY
Umatilla County Surveyors
Date 10-02
Rec'd By KK
No. 02-218-B

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells
OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-04