


History of original corner establishment:

Corner not set in 1881 by George S Pershin under General Land Office Contract No. 430.
None.




No record of subsequent remonumentation was found in county records.
Description of corner evidence found:

None

(See map of survey, dated December 1975)

Description of monument and accessories I established to perpetuate the original location of this corner

At corner position I set 2 1/2" X 30" iron pipe with brass cap marked as shown 27" in ground, from which:
A 5" Lodgepole Pine bears N 85° W, 5.8 ft. marked N 1/16 S3 BT.
A 8" Lodgepole Pine bears S 52° E, 10.7 ft. marked N 1/16 S2 BT.
Set steel fence post 5+ ft. North.



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Handwritten Signature
OREGON
JULY 10, 1864
DUANE I. GRIFFITH
644

Brass Washer nailed to BT blazes.
Used steel tape and magnetic compass with 19° 30' East declination.
Measured to center of all BTs.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the day of ..
..... by
(COUNTY OFFICIAL) (DEPUTY)

Q-905

29