


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner was originally established by Rufus S. Moore, U.S. Deputy Surveyor, under Contract No. 451, dated June 12, 1882. Surveyor General records state: Set a post 4 ft long 4 ins square 24 ins in the ground for the quarter corner to sections 29 and 30, from which:
A pine 9 ins. diam. bears S 80° E 6 lks. dist. marked: 1/4 S BT.
A pine 9 ins. diam. bears N 48° W 27 lks. dist. marked: 1/4 S BT.



Description of corner evidence found:

Nothing found of original evidence. This corner was not re-established on this survey.

Corner area was searched on 2 separate occasions with a 2 person crew. Total search time was 4 hours. 2 hours of professional land surveyor time was spent searching. A 150 foot radius search area was covered.

Corner area in an area logged within the past 20 years. There are signs of a burn in the area many years ago. None of the trees in area are old enough to be original corner accessories.

Corner search area was determined by closed traverse survey.

Description of monument and accessories established to perpetuate the original location of this corner:

August 4, 1994

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 12-31-94

Office of County Surveyor County of Umatilla
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the day of , 19
..... by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY
Umatilla County Surveyor
Date 8-4-94
Rec'd By KK
No. 94-106-C

*GPO-591-971, 1988