

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla. DATE: 04/04/08

CORNER DESIGNATION: L-13, The East One-Quarter corner of Section 16, Township 6 North, Range 36 East, W.M..

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by Odell & Lewis under GLO Contract No. 110., dated February 7, 1865. Notes state: Set 1/4 Sec. post. Drove charred stake; dug pits & raised mound, as per instructions.

MONUMENT AND ACCESSORIES FOUND: None. Corner falls in farmed field, with dim field line extending North-South.

MONUMENT MARKING DETAIL:

T6N R36E
1/4
S16|S15
2008
PLS 1106

MONUMENT SET: Reestablished corner position by single proportionate measure between the Southeast Corner and Northeast closing corner of Section 16. At reestablished corner point, set a 2 3/8" brass cap on a 1 1/4" x 30" galvanized iron pipe with cap buried 18" below ground level, marked as shown in "Monument Marking Detail".

New accessories:

- A silver deep-1 magnet bears North 57° East, 29.1 feet.
 - A purple deep-1 magnet bears South 34 1/2° East, 34.2 feet.
 - A blue deep-1 magnet bears South 35° West, 30.2 feet.
 - A orange deep-1 magnet bears North 47° West, 22.8 feet.
- All deep-1 magnets are buried 20" below ground level with bearing object signs.

LOCATION AND COMMENTS: Corner falls in dim North-South field line between fields.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 857617.97
E = 8758863.35

FIRM: Wells Surveying
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells, LSIT

\6N36L13

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Renews 6-30-10