

OREGON CORNER RESTORATION FORM

COUNTY: Washington

DATE: 06/17/2014

CORNER DESIGNATION: K-13 WA, Township 6 North, Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Walla Walla County Survey Bk. S, Pg. 221 Shows a rock 14" x 10" x 8" marking the corner to sections 15 and 16, Washington.

Paul Tomkins found an 8" x 10" x 15" stone with "WA" chiseled on the south side, as shown on Umatilla County Survey 05-134-C.

MOUNUMENT AND ACCESSORIES FOUND:

Remnants of rock pile base, with loose rocks were found scattered downhill from pile, which likely came loose. Found a small piece of old pink flagging, approximately 1.50' feet from rock base.

MOUNUMENT MARKING DETAIL:

MOUNUMENT AND ACCESSORIES SET:

No new monument or accessories set.

LOCATION AND COMMENTS:

Corner is on an east facing grassy slope, +/- 70 ft. north of brush line. Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 859377.01

E = 8791746.77

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

FIRM: HDJ Design Group
5 N. Colville, Suite 200
Walla Walla WA 99362

WITNESSES: Thomas J. Boshart
Felipe G. Hernandez



RENEWS 12/31/15

6/29/2015