

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 12/18/2014

CORNER DESIGNATION: T-13, Quarter Corner Section for Sections 28 and 27, Township 6 North, Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set stone 12x13x24 around stone for quarter section.

MOUNUMENT AND ACCESSORIES FOUND:

No evidence found.

MOUNUMENT MARKING DETAIL:

LS 02820
T6N R37E
S28 | S27
 1/4
12/2014

MOUNUMENT AND ACCESSORIES SET:

At the surveyed position, set a 2½" brass cap on 1½" galvanized iron pipe, 8" above ground, marked quarter corner of Sections 28/27 T6N, R37E by LS 02820 on 12/2014, from which:
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N43°W, 15.00 feet.
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N44°E, 15.00 feet.
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S44°W, 15.00 feet.
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S46°E, 15.00 feet.

LOCATION AND COMMENTS:

Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 848192.76
E = 8790710.57

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

FIRM: HDJ Design Group
5 N. Colville, Suite 200
Walla Walla WA 99362

WITNESSES: Joseph R. Latimer
Cory A. West



Greg E. Flowers
OREGON
JUNE 30, 1997
GREG E. FLOWERS
02820LS

RENEWS 12/31/15

06/29/2015