

# OREGON CORNER RESTORATION FORM

COUNTY: Umatilla      DATE: 1/15/2015

**CORNER DESIGNATION:** T-5, Quarter Corner Section for Sections 30 and 29, Township 6 North, Range 37E, W.M.

**PREVIOUS RENEWALS/SURVEYS ETC:**

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set post and marked stone monument and pits for quarter section.

**MOUNUMENT AND ACCESSORIES FOUND:**

No evidence found.

**MOUNUMENT MARKING DETAIL:**

LS 02820  
T6N R37E  
S30 | S29  
    1/4  
1/2015

**MOUNUMENT AND ACCESSORIES SET:**

At the surveyed position, set a 2½" brass cap on 5/8" iron rebar, 20" below ground in bedrock, marked quarter corner of Sections 30/29 T6N, R37E by LS 02820 on 1/2015, from which:  
Buried "Deep-1" Pink magnet with bearing tag 20" below ground, bears N39°W, 10.00 feet.  
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N53°E, 23.00 feet.  
Buried "Deep-1" Blue magnet with bearing tag 20" below ground, bears S43°W, 10.00 feet.  
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S56°E, 24.70 feet.

**LOCATION AND COMMENTS:**

Corner falls in a farmed field on a west slope 20 ft. west of a N-S fence that jogs east 60 ft. about 60 ft. north of the corner and then continues north. Bearings taken with Silva hand compass and distances measured with a steel tape.

**OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:**

N = 847808.09  
E = 8780360.78

**COMPASS DECLINATION:** 15° East


**SURVEYORS' SEAL:**

**FIRM:** HDJ Design Group  
5 N. Colville, Suite 200  
Walla Walla WA 99362

**WITNESSES:** Joseph R. Latimer  
Cory A. West



*Greg E. Flowers*



RENEWS 12/31/15

*06/29/2015*