


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1881 by Meldrum & Campbell, under General Land Office Contract No. 380.

Surveyor General records state:

Set a fir post for cor. to secs. 1, 2, 35 & 36 from which a
 Fir 16 in. dia. bears N57°E, 58 lks. dist.
 1" 24 " " " N13°W, 45 " "
 " 20 " " " S41°W, 63 " "
 Pine 36 " " " S67°E, 75 " "



Description of corner evidence found:

Did not find the original post, but a 1/2" galvanized pipe had been driven near the corner location. Three of the BT's are alive and in good condition. The NW BT has been cut and is a deteriorating stump.

Description of monument and accessories established to perpetuate the

original location of this corner Established the corner location using the BT info of above and set a 2"x30" galvanized pipe with a flared end and 2 1/2" brass cap 24" in the ground. Surrounded monument with a rock mound 6" high and 30" in diameter. Set a 4"x4"x6" redwood post 20" in the ground 4' West of the monument with signs 54-2 & 54-4 as a guard post for the corner. Scalped bark and painted red band around Bearing Trees and posted signs 54-3 with the following information:

Stump	S13°E	29.7'		
22" D. fir	S57°W	39.2'		
28" P. Pine	N67°W	51.6'	New BT was scribed	
24" D. fir	N41°E	43.5'	in upper blaze;	and in lower blaze;
New- 10" P. Pine	S68°E	60.3'	T6S R31E S35	BT, along with a brass nail & washer stamped RLS 699

This corner is on the line between Grant & Umatilla Counties.

REGISTERED PROFESSIONAL LAND SURVEYOR

I hereby certify the above corner monument was re-established as herein described on November 6, 1974.

Leland Lee Myers

OREGON JULY 9, 1965 LELAND LEE MYERS 6319

74828

Office of _____ County of Grant
 State of Oregon, hereby certify that the within instrument was filed in this office
 for record on the 19 day of November, 1974, by Patty [Signature]
 _____ (COUNTY OFFICIAL) by [Signature] (DEPUTY)



INDEXED

2.2