

USDA-FOREST SERVICE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Index File No. S-17

Tract or Survey No. _____ Cor. No. _____


T. 6S R. 32E

R.D. N. Fk. J. Day County Umatilla

Merid. W.M.

N.F. Umatilla State Or.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

2 1/2" iron pipe with brass cap mtd. N1/16
827/826
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

P. Pine, 10", s57 1/2° E, 13.2', with scribing visible
P. Pine, 12", N74 1/2° W, 15.8', " " "

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner falls on SEly slope. From K tag on 070 rd.. follow posted line 518' east.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature *F. J. Munro*

Title *L.S.*

Division

Headquarters

Date *11/19/86*

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None..

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BTs have blaze and 6" band painted red, BT tags and "Land Survey Monument" signs.. 6' steel fence post with "Land Survey Monument" sign within 5' of the corner.

10

Work Done By F.S. Munro Title L.S. Date 11/1/86 State Registration No. 1832
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

12

Index File No. S-17 T. 68 R. 32E M. W.M. Tract or Surv. No. _____ Cor. _____

13