


History of original corner establishment:

The corner was originally established by the BLM in 1968 under Group No's. 350 and 643, as follows:
Set an iron post in a mound of stone with a brass cap attached which is marked as shown in the diagram, from which: A 12" fir bears S70°E, 25 links (16.5 feet). A 7" fir bears S31°W, 15 links (9.9 feet).
On October 30, 1986, Fayette S. Munro, PLS 1832, found the BLM brass capped iron pipe monument surrounded by a mound of stones. The cap was marked as shown in the diagram above, from which: A 8" White Fir with a healed blaze bears S31°W, 9.9 feet. A 13" sickley Douglas-fir with a healed blaze bears S70°E, 16.5 feet. Munro scribed a new bearing tree; A 12" Tamarack bears S66°45'E, 91.7 feet.



Description of corner evidence found:

A 2 1/2" iron pipe with a 3 1/4" brass cap attached protruding 3" above the ground and surrounded by a mound of stones. The cap is marked with the BLM logo and as shown in the diagram above, from which:
A 13" fir snag with burnt out blaze bears S70°E, 16.9 feet.
A 9" fir snag with a single healed blaze bears S31°W, 9.7 feet.
A 12" Western Larch snag with a single healed blaze bears S67°30'E, 91.7 feet.

Description of monument and accessories established to perpetuate the original location of this corner:

I establish the following new references:

- A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S30", attached at ground level, bears S79°E, 68.4 feet.
- A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S25", attached at ground level, bears S4°W, 77.1 feet.

I hereby certify the above corner was perpetuated as hereon described on March 26, 1997. Magnetic declination: 20°E.



Office of... County of...
State of... I hereby certify that the within instrument was filed in this office for record on the... day of..., 19...
..... by
(COUNTY OFFICIAL) (DEPUTY)

RECEIVED BY
Umatilla County Surveyor
Date 4-97
Rec'd By BK
No. 97-73-R