

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**


**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner was originally established under GLO Special Contract, dated May 4th, 1887, executed by Currin and Noland. Surveyor General field notes state:

Set a post 36x3x3 in. 24 in. in ground for 1/4 sec. cor. marked 1/4S on N. face, from which  
A pine 6 in. in dia. S45°E dist. 32 lks. mkd. 1/4 S BT  
A pine 6 in. in dia. bears N20°W dist. 92 lks. mkd. 1/4 S BT

Corner was not found and position was placed by proportion in Umatilla County Surveys S-002-B and 95-221-B.

T 1 S R 35 E E-11



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

No evidence found.

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:**

At proportionate position, I set a 2 1/2" x 30" aluminum pipe, 28" in the ground, with 3" aluminum cap marked as shown below, from which:


**NEW BEARING OBJECTS:**

A 10" Douglas Fir bears North 55° East, a dist. of 9.55 feet, marked 1/4 S4 BT.  
A 14" Douglas Fir bears South 61° East, a dist. of 14.35 feet, marked 1/4 S9 BT.  
A 4" White Fir bears South 41° West, a dist. of 10.60 feet, marked 1/4 S9 BT.  
A 5" White Fir bears North, 39° West, a dist. of 17.70 feet, marked 1/4 S4 BT.

Set steel fence post approx. 1.5 ft. East

I hereby certify that the corner was monumented October 21st, 2025

Witness: Kyle Tucker, Jason Hatfield



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2027

I use a tape and compass in the establishment of the new bearing trees. Bearings are measured from the center of the aluminum cap to a brass washer marked "OPLS 83571" tacked to the BT blaze using 14° East for declination. Distances are measured to from the center of the aluminum cap to a 60D spike in the center right base of the tree.