CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T1SR35EE-14

DESCRIPTION OF CORNER EVIDENCE FOUND:

None found. A fence corner to South and East bearing fence lines bears approx. 45 ft. West.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

A 9" Lodgepole Pine bears South 83° West, a dist. of 10.00 feet, marked W 1/16 S10 BT. A 9" Lodgepole Pine bears North 9° West, a dist. of 8.00 feet, marked W 1/16 S3 BT.

Set steel fence post approx. 0.5 ft. East


I hereby certify that the corner was monumented November 4, 2025 $\ensuremath{\varepsilon}$

Witness: Kyle Tucker, Nick Peckham

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2027



I use a tape and compass in the establishment of the new bearing trees. Bearings are measured from the center of the aluminum cap to a brass washer marked "OPLS 83571" tacked to the BT blaze using 14° East for declination. Distances are measured to from the center of the brass cap to a 60D spike in the center right base of the tree.