

# OREGON CORNER RESTORATION FORM

SECTION 13 TOWNSHIP 4 NORTH RANGE 27 EAST L-25

COUNTY : UMATILLA DATE 10-2002

CORNER DESIGNATION

EAST 1/4 CORNER

- CONDITION REPORT ONLY
- NOT FOUND
- RENEWED
- UNCOVERED
- SURVEYED IN
- REFERENCED

PREVIOUS RENEWALS / SURVEYS, ETC.


ORIGINAL SURVEY BY HAFT IN 1860. CONTRACT #93.  
DEPENDENT RESURVEY BY GOULD IN 1941.  
IN 1999 EDWARDS SET 5/8"X30" IRON REBAR WITH PLASTIC CAP #951 FROM GOULD'S  
BRASS CAP WITNESS CORNER 19.80 FEET EAST.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

FOUND A 5/8"X30" IRON REBAR WITH PLASTIC CAP #951 10" BELOW THE SURFACE OF THE ROAD.  
FOUND 2 1/2" B.C. W.C. ON 1" IRON PIPE 18" ABOVE SURFACE (GOULD 1941) STAMPED 30W  
(30 LINKS OR .30 CHAINS OR 19.80 FEET) EAST OF CORNER.  
FOUND A 1/2" IRON PIPE IN THE SOUTH EAST CORNER OF A CENTER PIVOT PAD BEARS  
N 20°49'20" W 53.32 FEET  
FOUND A 2 3/8" BRASS CAP ON A 1"X30" IRON PIPE BEARS N 89°53'25" W 19.89 FEET  
FOUND AN ALUMINUM TAG STAMPED #951 ON A POWER POLE BEARS S 80°33' W 17.10 FEET

MONUMENT DETAIL

SKETCH



MONUMENT SET ( PROCEDURES AND DESCRIPTION )

NA

NEW ACCESSORIES FROM WHICH

NA

LOCATION AND COMMENTS

AT THE INTERSECTION OF WALKER  
ROAD AND BRIDGE ROAD GO SOUTH  
1/2 MILE TO CORNER.

COMPASS DEC.

FIRM/AGENCY  
EDWARDS SURVEYING  
P.O. BOX 763  
HERMISTON, OREGON 97838

PARTY CHIEF  
CURTIS FAVOREL

NOTES

WITNESS  
RICK SMITH

SURVEYOR'S SEAL

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*G. Dennis Edwards*

OREGON  
JULY 16, 1971  
G. DENNIS EDWARDS  
9 5 1

RENEWS 12/31/2003

03-50-9