

OREGON CORNER RESTORATION FORM

Section 23,24 Township 4N Range 37E W.M.
County Umatilla Date 8/1/93
CORNER DESIGNATION: P-21

Previous Renewals/Surveys, etc. This corner was resurveyed by Charles L. & William C. Campbell under contract No. 733, dated March 22, 1901. They set a basalt stone 24 x 12 x 5 at 40.36 chains for W. C. to the 1/4 sec. cor. 18 ins. in the ground marked, WC1/4 on the west face from which:
A tamarack 10 ins. diam. brs. N.24°30'E., 17 lks. dist. marked WC 1/4 S24 BT
A tamarack 10 ins. diam. brs. N.6°45'W., 91 lks. dist. marked WC 1/4 S23 BT

Monument(s) & Accessories Found: (Condition and Source) Found a basalt stone 24 x 12 x 5 set 18" in the ground with WC 1/4 clearly marked on the west face a down and rotten tamarack with blaze and scribing brs. N.13°W., 57.3 ft.

Monument Detail:

T4N R37E
WC $\frac{1}{4}$
4
S23 | S24
1993
OR 1106

Monument Set (Procedures and Description): Set a 1 1/2" x 30" iron pipe with a 2 1/2" brass cap marked as indicated in the monument detail 20" in the ground with a mound of earth and stone to the top. Set the corner rock beside the monument as a witness.

New Accessories:

A 24" fir brs. N.29°W., 35.1 ft. marked T4N R37E S23 BT
A 10" fir brs. N.54°E., 37.5 ft. marked T4N R37E S24 BT
A 18" fir brs. S.85°W., 18.5 ft. marked T4N R37E S23 BT
A 20" fir brs. S.56°E., 29.8 ft. marked T4N R37E S24 BT
A steel fence post with a Land Survey Monument sign attached brs N. 3.2 ft.
Location & Comments: The corner falls on top of the north bank of a 30' deep ravine 200' east of Elbow creek, a 25" fir with a Boise Cascade location sign attached brs. S. 7.0 ft.

Compass Declination: 18° E
Firm/agency: Tomkins-Wells Joint Venture
Land Surveying
P.O. Box 1696
Pendleton, Oregon 97801

Party Chief: Greg Flowers
Notes: Greg Flowers
Witness: Todd Rosenbalm

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

expires 12-31-94

93-64-C