


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner previously established by James Hambleton in Survey N-65-B dated 2-15-77. Umatilla County Survey Record shows Hambleton setting a 5/8" x 30" iron pin.

T 4 N R 37 E T-15



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

Found a 5/8" iron pin, approx. 1" below ground, with illegible markings on a crumbling yellow plastic cap and in a 2 ft. collar of embedded stone.

SEE SURVEY FOR MANULIFE FILED AUGUST 2022

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position of found pin, I add a 2 1/2" aluminum cap, marked as shown, to the iron pin, from which:


**NEW BEARING OBJECTS:**

- A 5" White Fir bears North 56° East a dist. of 21.60 ft., marked C1/4 S27 BT.
- An 8" Spruce bears South 22° East a dist. of 13.55 ft., marked C1/4 S27 BT.
- A 10" White Fir bears South 64° West a dist. of 25.50 ft., marked C1/4 S27 BT.
- A 6" White Fir bears North 20° West a dist. of 34.60 ft., marked C1/4 S27 BT.

Set steel fence post approx. 1 foot East

Falls approx. 10 ft. Southeasterly of fence corner to East and South bearing fence lines.

I hereby certify that the corner was perpetuated on July 27, 2022.  
Witness: Kyle Tucker, Dan Drum



Renewal Date: June 30, 2023

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.