

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 4N , R 37E. , W.M.

Corner Code No. V-19

Note: Monument marked as shown below


History of original corner establishment:

This corner was originally established by George S. Pershin, U.S. Deputy surveyor, under Contract No. 322, dated July 29, 1879.

The original notes state:

Set fir post on N.W. hillside for 1/4 sec. cor., from which:

A fir 20 in dia bears N 56° W 47 links.  
A fir 8 in dia bears S 34° E 31 links.



Corner No.  
Compass Declination: 18.0°

Description of corner evidence found:

Found 2" O.D. galvanized iron pipe by 24" long, 2" out of ground, origin unknown.

This pipe has been used as the corner on all surveys in this area since the 1950's.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position of the found 2" O.D. pipe, set a 2 1/2" brass cap on a 1 1/4" by 30" galvanized iron pipe 24" in the ground, and surrounded with a mound of earth and stone. Buried old pipe horizontally South of the new corner monument.

Marked 3 new bearing trees:

A 4" Englemann spruce bears N 5°E, 4.4', scribed "X" at breast height and BT at base.

A 8" Englemann spruce bears N 84°E, 34.1', scribed 1/4 S26 BT.

A 4" western larch bears S 40°E, 4.0', scribed "X" at breast height and BT at base.

Southeast corner of Parcel 2, Partition Plat no. 1991-07 bears East 57.0'.

Placed bearing object signs on bearing trees.

Set steel fence post 3' East of corner with a witness corner sign attached.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Will: R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19....

..... by .....

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO—788-276

RECEIVED BY

Umatilla County Surveyor

Date 9-9-77

Rec'd By KK

No. 91-75-C